



After grit blasting, leaks repaired with DurAlloy.



DuraWrap Primer applied.



DuraWrap Carbon Fiber, impregnated with DuraWrap Polymers, being wrapped around pipe section.



DuraWrap Saves Main Influent Pipe at Waste Water Treatment Plant

- Location:** Northeastern U.S.
Problem: Corroded & leaking main influent pipe.
Solution: Repair leaks with *DurAlloy*; reclaim pipe with *DuraWrap Carbon Fiber Pipe Wrap System*.
Cost: \$40,000 total turn-key project.
Savings: \$100,000+ replacement cost.



Completed DuraWrap System.

ENECON Ibérica · C/ St. Gervasi de Cassoles, 96-98 entlo. 3^a · 08022 Barcelona
· Telf: +34 93 211.15.30 · Fax: +34 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com