



After grit blasting, leaks repaired with DurAlloy.



DuraWrap Primer applied.



DuraWrap Carbon Fiber, impregnated with DuraWrap Polymers, being wrapped around pipe section.



## DuraWrap Saves Main Influent Pipe at Waste Water Treatment Plant

- Location:** Northeastern U.S.  
**Problem:** Corroded & leaking main influent pipe.  
**Solution:** Repair leaks with *DurAlloy*; reclaim pipe with *DuraWrap Carbon Fiber Pipe Wrap System*.  
**Cost:** \$40,000 total turn-key project.  
**Savings:** \$100,000+ replacement cost.



Completed DuraWrap System.