


Oil Company in Thailand Repairs 22 'Problem Areas' with DuraWrap



Client: Major oil company

Location: Thailand

Problem: 20" diameter pipe was severely rusting in 22 different locations.

Solution: Original galvanized coating was removed. Rusted areas were manually prepared by grinding and wire brushing. *DurAlloy* was used to repair any damaged areas on the pipe. *DuraWrap Primer* was applied followed by two layers of *DuraWrap Carbon Fiber System*.



Before



After