ENECON® NEWS

MT-161

After 4+ Years Of Service In An Alumina Refinery, CeramAlloy CBX Is Still In Excellent Condition



Client:

Australian Alumina Refinery

Problem:

Calciner screws, subjected to extreme abrasion typically only last 12-18 months.

This screw (image 1) was protected with CeramAlloy CBX and put back into service for over 4 years.

After brush blasting clean, the CeramAlloy CBX is shown to still be in excellent condition (image 2).

After 4+ years in service.

After cleaning, the CBX is still in excellent condition.

PROENECON SYSTEMS, S.A.· C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
·Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com

Copyright ©2018 by ENECON® Corporation.

REPAIR - DON'T REPLACE®