



## When All Else Failed, Only ENESEAL HR Stopped the Leaks in Israel



As reported by our Field Engineering Specialist for the ENECON Distributor in Israel...

“These pictures show a joint between an old and a new building. Water was leaking through the joint. They tried all kinds of solutions (silicone, tar, etc.) with no success”.

Although every-thing they could come up with in the way of conventional approaches and materials was tried, none proved successful.

**The leaks were finally stopped; but -- Only ENESEAL HR did the job!**



ENECON Ibérica · C/ St. Gervasi de Cassoles, 96-98 entlo. 3ª · 08022 Barcelona  
· Telf: 93 211.15.30 · Fax: 93.253.11.31  
Website: [www.proenecon.com](http://www.proenecon.com) · Email: [eneconib@proenecon.com](mailto:eneconib@proenecon.com)