



CHEMCLAD GP Still Perfect After 8 Years In Very Busy Train Station In Northeastern USA



Conventional Paint System Applied 8 Years Ago & What It Looks Like Now



CHEMCLAD GP Applied 8 Years Ago Is Still In Perfect Condition



The above newsletter (CH-067) highlighted the repair and protection of a northeastern US commuter train waiting room floor completed 8 years ago. The surface of the floor was prepped and **CHEMCLAD P4C** was used as a primer. Two coats of **CHEMCLAD GP** were then applied with an aluminum oxide broadcast for slip-resistance properties.

At the same time in a different waiting room, at the same station, a conventional paint system was applied to the floor.

As you can see from these photos, the conventional paint system failed, almost completely. But after 8 years, the **CHEMCLAD GP** is in near perfect condition and still performing as originally intended.

PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com