

80% - 90% Of Roof Problems Typically Occur On 10% - 20% Of Roof Areas



A shoe factory in Romania had a 45,000+ square foot metal roof that was leaking. Water was seeping through common problem areas near gutters as well as ventilation equipment protrusions.

Roof leaks like these can damage inventory, electrical equipment as well as create workplace safety hazards. The shoe factory management needed a trusted solution to solve their problem.

The local ENECON Distributor was contacted and ENESEAL CR was recommended.

All of the areas were pressure washed and wiped clean with acetone. Roofing seam tape and patching material was used to seal any big holes. Two coats of ENESEAL CR were applied to provide a seamless, weather resistant, protective 'skin'.

This two-day application was a complete success.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona.

Tel: 93.211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com