
## ELECON® NEVS



## Moroccan Nightclub Uses DuraQuartz, DuraFill & ENECLAD FPS to Repair & Protect Crumbling Concrete



Problem: The concrete entrance steps were crumbling, creating a safety hazard. Previous mortar repairs proved to be ineffective. An additional concrete patio slab was also beginning to show signs of erosion.

Solution: The stairs were manually prepared and ENECRETE

DuraQuartz was used to rebuild the step edges. The steps were then painted to match the building's exterior.

ENECRETE DuraFill was also used to repair the damaged patio slab. ENECLAD FPS was applied as a top-coat to provide long term protection to the patio floor.















PROENECON SYSTEMS, S.A.· C/ Electricitat, 6. Pol. Ind. La Torre  $\cdot$  08760 - MARTORELL. Barcelona. ·Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com