

Pennsylvania Gas Station Pump Island Curbs Rebuilt With DuraQuartz & DurAlloy



A very popular chain of Pennsylvania gas stations & convenience stores was experiencing severe corrosion and erosion on their gas pump island curbs. It was a potential hazard to customers and employees in addition to being very unsightly.

The maintenance management team contacted the local

ENECON Field Engineering Specialist to provide a fast, economical and proven solution to this problem.

After all the loose material was removed and the area cleaned, the concrete curb was rebuilt with *ENECON DuraQuartz*. The half-round metal curb edging was rebuilt with METALCLAD DurAlloy.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com