



After



Before



School District Solves Safety and Unsightly Wall Issues

A northeastern school district needed to upgrade their facilities' hallways and restrooms. The original wall surfaces were ceramic tiles that had become cracked with missing tiles in many locations. This condition was a serious safety concern for the district officials.

The school district turned to their local ENECON Distributor to propose a cost-effective solution that would solve the safety issues and result in a new, low maintenance, aesthetically pleasing wall system.

Following the appropriate surface preparation, which included abrading and cleaning the tiles, the walls were treated with a 4-coat **ENECRETE DuraFill** system. This system included rolling/brushing

a layer of **DuraFill** and then manually broadcasting colored decorative vinyl chips/flakes into the wet **DuraFill** and letting this first layer set overnight. After it has dried a trowel is used to smooth out and remove any loose chips/flakes.

Additional similar layers – a total of 3 – were applied each day followed by a final layer of just the **DuraFill** clear resins – about one week total.

This **DuraFill** broadcast system application also included filling in any damaged and missing tiles with **ENECRETE DuraQuartz**.

This attractive wall finish provided the school with a long-term solution to what had been a troublesome maintenance issue.

PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com