



ENECLAD FPS 2000 Revitalizes Main Entrance For This Pennsylvania Manufacturer

The main entrance for this manufacturing company was showing its age. The concrete was cracked and deteriorated. The conventional approach would have required removing the old concrete and pouring new steps and walkway. The corresponding downtime would have presented problems since this entrance was the main access to the facility.

They wanted a long-term repair that would only close the entrance for as short a time as possible. The answer: The ENECON Engineering Team.

The concrete was first power washed and allowed to dry. DuraQuartz was used to repair all the cracks and heavily damaged areas. ENECRETE Self Priming Screed (SPS) was then applied to smooth out the rough

concrete surface. Finally, two coats of ENECLAD FPS 2000 were installed by roller and a #46 aluminum oxide aggregate was 'back-rolled' into the topcoat to provide for a safety, non-slip surface. This project was accomplished in just two days to the complete satisfaction of the building owners.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona.

Tel: 93.211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com