

Maryland Hotel Selects DuraQuartz & FPS 2000 to Repair & Protect Busy Walkway



This hotel in Maryland was confronted with a potentially costly as well as disruptive problem for guests and staff. The walkway pictured above had been covered with a rubber runner for a long period of time. When the runner was lifted off the walkway the hotel management discovered severe cracking to the walkway surface.

In order to avoid potential injury to guests and staff it was decided that the walkway had to be repaired or replaced completely.

The local ENECON Dealer was contacted in order to see if he could suggest a quick yet cost effective solution to this safety problem.

Since the walkway was generally sound, he suggested that all the cracks be repaired with ENECRETE DuraQuartz and then the entire walkway should be sealed and protected with ENECLAD FPS 2000.

The walkway was first cleaned and prepared by grit blasting.

DuraQuartz was used to fill, repair and level all the cracked areas. FPS 2000 was then used to seal and protect the entire walkway from future deterioration.

The hotel management was very satisfied with the results and with the money they saved utilizing the ENECON solution.

PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona.

Tel: 93.211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com