

Starch Factory in Thailand Solves Serious Mineral Scale Problems in Their Cooling Tower With ENEFLOW Power Cells



Note: Severely restricted sprinkler flow



ENEFLOW Installation

This major starch producer in Thailand had an on-going problem with severe calcium carbonate scale build-up in their cooling tower sprinkler pipe.

An ENECON Field Engineer in Thailand suggested an ENEFLOW installation to eliminate, or at least reduce, the scaling problem.

Two pair of ENEFLOW 5000's were installed on the cooling tower's feed pipe and 60 days later the scale had virtually disappeared.

According to the ENECON Engineer, the plant engineers were completely satisfied with the results obtained.



Note: Much Improved sprinkler flow