



## Town Park Uses DuraQuartz & ENESEAL to Repair & Protect Concrete Ceiling



**Client:** Parks and Recreation Department in New York State.

**Problem:** The park's entrance ceiling was showing signs of water damage, spalled concrete, exposed rebar and missing failed coating. The Town was concerned that loose concrete could create a safety issue for park users.

**Solution:** A combination of power washing and hand grinding was used to thoroughly clean the surface and remove any loose concrete. Any exposed rebar was coated with **ENESEAL CR** and all damaged concrete areas were repaired with **ENECRETE DuraQuartz** with *light weight aggregate*. **ENESEAL HR** was used as a final topcoat.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona.

Tel: 93.211.15.30 · Fax: 93.253.11.31

Website: [www.proenecon.com](http://www.proenecon.com) · Email: [eneconib@proenecon.com](mailto:eneconib@proenecon.com)