



CeramAlloy Protects Wood Chip Cyclone Separator at a Major Paper Mill in South Carolina



This large paper mill located in South Carolina wanted to repair and protect their wood chip cyclone separator. The engineers at the mill turned to their local ENECON distributor, ENECON South East, headed by Tripp Waynick.

They recommended CeramAlloy CP+

[AC] for filling/repairing holes in the metal and then applying two coats of CeramAlloy CL+ [AC] to protect approximately 500 sq. ft. of the separator.

The unit was 100 ft. above the ground so the ENECON application team got "plenty of exercise".