

Outdoor Fountain At Pennsylvania Landmark Building Is Repaired With CeramAlloy CL+AC



This fountain, located in the outdoor dining area of a restaurant, was in need of serious repair. The fountain's tiles were coming loose and very difficult to color match and replace. The replaced tiles wouldn't hold in place very long either.

This restaurant was built in the 1700's and has had local Pennsylvania landmark status for over 100 years. The building's maintenance team has had previous successes with ENECON products so the local ENECON Field Engineering Specialist was contacted to help find a solution.

The fountain was drained of its water and all of the tiles were removed. The concrete surface was manually prepared with a grinding wheel. Two

coats of CeramAlloy CL+AC were then applied to provide fluid flow erosion and corrosion resistance.

This project was completed in just four days with little disruption to the restaurant. The maintenance team was thrilled with the results and have reported that management receives compliments from the restaurant diners almost daily.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com