ELECON REVIS



The copper gutters on this gymnasium's roof were leaking onto the wood floors below. The school needed a quick, yet cost-effective repair solution. The repair material had to exhibit out-standing adhesion, elongation and UV resistance.

.....

Matt Goldberg, ENECON's Sales Director for the Mid Atlantic Region, was called in to provide his recommendations. Matt immediately recommended ENESEAL. Since the school already had used ENESEAL HR successfully on other problem roof areas in the past, they readily agreed to use it again for this application.

Carl Durham, ENECON's National Projects Manager, quickly mobilized one of his crews and the leaking gutters were repaired and sealed with the ENESEAL system in just a few days.







PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona. Telf: 93.211.15.30 · Fax: 93.253.11.31 Website: www.proenecon.com · Email: eneconib@proenecon.com

Copyright © 2002 by ENECON[®] Corporation.

ES009_ENESEAL_at_PA_School_Gutters.pdf