



Italian Coast Guard Selects CHEMCLAD XC To Solve Corrosion Issues



This Italian Coast Guard vessel had been experiencing some severe corrosion on its hull.

ENECON Italia was contacted to help find a quick and cost effective solution.

The affected area was first grit blasted to remove all corrosion and prior coatings. The entire area was then rebuilt with 6 mm of CeramAlloy CP+AC and reinforcement mesh.

This repaired area was then protected with CHEMCLAD XC.

The ship's command was so pleased with the results that many other vessels in this class, as well as other classes, have been repaired and protected with ENECON products.

