




U.S. Naval Air Station




Solves Potential Safety Problems With ENECRETE DuraQuartz



BEFORE
DuraQuartz

Matt Goldberg, ENECON's Regional Sales Director, was called in by the facilities engineer at a U.S. Naval Air Station located in Pennsylvania. He was asked to provide a recommendation for repairing a damaged walkway to an administration building on the base.

The choice was obvious: **ENECRETE DuraQuartz** was perfect for this application. Its ease of use, its ability to be 'feather edged', its outstanding adhesion to the existing concrete, and its overall durability made DuraQuartz the best, cost-effective choice to repair the ramp.



AFTER
DuraQuartz

The concrete ramp had a number of tripping hazards due to spalled and cracked concrete. The repairs, however, had to be done quickly, with minimum disruption to the building's staff.

Of course, Matt was there during the entire project to insure that the repairs went smoothly and were completed quickly.



ENECON Ibérica · C/ St. Gervasi de Cassoles, 96-98 entlo. 3ª · 08022 Barcelona
· Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com