

DuraQuartz & CHEMCLAD Used to Repair Tile Floor at Pennsylvania Hospital Kitchen



Portions of tiles where grout had failed were chipped away.



Some tiles were in such poor shape that they were completely removed.



DuraQuartz was used to repair the failed tile sections.



CHEMCLAD XC was applied over the DuraQuartz as well as over the first row of tiles in order to provide a uniform appearance. The entire project was completed in one night!