

## Every Day Concrete Problems Are No Problem With DuraQuartz



The facilities' engineers of a major pharmaceutical firm located in New Jersey, were "extremely impressed" with the professionalism and rapid response of the local ENECON Mid Atlantic Field Engineering Team. As these pictures illustrate, this routine

yet potentially dangerous concrete problem was quickly repaired with ENECRETE DuraQuartz.

Forms were used to "shutter" the DuraQuartz repair. After these were removed, SpeedAlloy was used to fill in

any irregularities in the DuraQuartz surface.

The repaired areas were then sanded and a coat of FPS 2000 was applied to finish off the repair and make it look "perfect".