

ENECON DuraQuartz Repairs Damaged Concrete at Ice Rink



The parking area for the Zamboni machine used to groom the ice at an ice rink at a New Jersey prep school was severely damaged from a combination of melting ice and the studded tires on the Zamboni machine.

After pressure washing the floor, the facility's maintenance crew applied the DuraQuartz to rebuild and resurface the damaged concrete.

The entire project took only a few hours to complete.

