


## ENECON Poland Solves Serious Erosion/Corrosion Issues Caused by Water Intrusion in Sumps & Manholes for Polish Water Treatment Authority



ENECON Poland's Field Engineering Team was asked to help solve some serious erosion and corrosion issues accelerated by water intrusion problems caused by hydrostatic pressure in these sumps and manholes. The Warsaw Wastewater Treatment Authority tasked ENECON Poland to repair and protect some of their most severely damaged manholes in order to demonstrate

the effectiveness of our high performance polymer systems for these types of repairs throughout their extensive infrastructure.

Over \$10,000 of ENECRETE WS and WP, CHEMCLAD SC and ENESEAL HR were used to seal, repair and protect these manholes. The extraordinary results, illustrated in these pictures, speak for themselves.



ENECON Ibérica · C/ St. Gervasi de Cassoles, 96-98 entlo. 3ª · 08022 Barcelona  
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: [www.proenecon.com](http://www.proenecon.com) · Email: [eneconib@proenecon.com](mailto:eneconib@proenecon.com)