




Air Extraction Fan Blades From Australian Mining Operation Re-Built & Protected With CeramAlloy

These aluminum air extraction blades had eroded due to the fine particles that were sometimes present in the air in the mine. The mine's maintenance

engineers wanted a quick and cost effective method to repair these fan blades and provide them with long-term protection from future erosion damage. They selected

CeramAlloy CP+AC and CL+AC because of the ease of application and the outstanding erosion and corrosion resistance that the CeramAlloy system provides.

These step-by-step photos clearly illustrate the outstanding results.



ENECON Ibérica · C/ St. Gervasi de Cassoles, 96-98 entlo. 3ª · 08022 Barcelona
· Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com