

European Refinery Repairs & Protects Cooling Water Pumps With CeramAlloy

At this major refinery located near Antwerp, Belgium, erosion and corrosion problems were a constant maintenance issue for the plant's engineers. A number of years ago, they decided to repair and protect their cooling water pumps with

CeramAlloy CP+AC and CL+AC.

The maintenance engineers have been delighted with the results and this series of photos illustrates a typical cooling water pump repair procedure.



ENECON Ibérica · C/ St. Gervasi de Cassoles, 96-98 entlo. 3ª · 08022 Barcelona
· Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com