



ENESEAL CR Prescribed to Repair Northern California Hospital's Cooling Tower Piping & Electrical Cabinets




Client: Northern CA Hospital

Problem: Due to neglect and lack of maintenance, these cooling tower pipes and electrical cabinets were suffering from severe corrosion.

Solution: Extremely corroded areas were prepared by wire wheel brush followed by high pressure washing. Two coats of **ENESEAL CR** were then spray-applied providing years of corrosion and UV protection.

Cost: This \$70,000 turn-key project was completed in just one week and has now led to protecting other areas of the hospital suffering from similar conditions.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona.

Telf: 93.211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com