


## Pennsylvania Hospital Stops Leaking Dishwashing Tray Seams in their Kitchen with FLEXICLAD ER



ENECON has solved many 'standard' problems at this Pennsylvania hospital - repairs to cooling towers, chillers, floors, pipes, etc.


The hospital's maintenance engineers contacted the local ENECON Fluid Flow Systems Specialist with what they considered an 'unusual' problem. The seams of their stainless steel dishwashing tray line were leaking. This was causing slip/fall accidents, constant clean-up and generally unsanitary conditions.

They had tried to fix the leaks numerous times with

caulks, but with no success. It was quickly agreed that FLEXICLAD ER would be used to solve this problem.

The area's were manually prepared with sandpaper, then cleaned thoroughly. FLEXICLAD ER was applied, with no primer needed. The area was ready to be put back into action the next morning with no odor and no downtime.

The hospital maintenance staff was pleased with the results and ENECON continues to be the hospital's 'problem solver'.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona.

Tel: 93.211.15.30 · Fax: 93.253.11.31

Website: [www.proenecon.com](http://www.proenecon.com) · Email: [eneconib@proenecon.com](mailto:eneconib@proenecon.com)