ENECON® NEWS
CH-010

Major Hotel in Boston Solves Chemical Corrosion Problems in Their Laundry With CHEMCLAD SC



At this chemical storage area in a large Boston hotel's laundry, chemical corrosion had severely damaged the diamond plate platforms.

The hotel's facilities engineer wanted a more durable as well as cost effective solution to their usual paint or replace procedures.

He turned to ENECON North East for some guidance. The local ENECON Fluid Flow Systems Specialist suggested grit blasting the diamond plate and then applying two coats of **CHEMCLAD SC**.

The hotel engineers are delighted with the results and the cost savings over traditional repair or replacement procedures.

CHEMCLAD SC...

- **Cost Effective!**
- **Easy to Use!**
- **Solvent Free!**
- **Highly Durable!**

Excellent Chemical Resistance!

PROENECON SYSTEMS, S.A.· C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
·Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com

Copyright © 2002 by ENECON® Corporation.