

## Spanish Nuclear Power Plant Repairs & Protects Cooling Water Storage Pools with DuraQuartz, DuraFill & CHEMCLAD SC



These massive concrete storage pools at a major nuclear power station in Spain needed to be repaired and protected.

The plant engineers selected ENECON's high performance repair composites (**DuraQuartz** and **DuraFill**) to repair any damaged concrete

and to screed and prime all the concrete surfaces of the pools, thus insuring a very smooth and crack-free surface.

One coat of **CHEMCLAD SC** was then applied over the entire pool area in order to provide a water-proof and maintenance-free surface.

This prestigious **\$1.5 MILLION project**, which also included two cooling tower pools and associated channels, was completed on time and within budget by ENECON Ibérica to the complete satisfaction of the plant engineers.



ENECON Ibérica & France · C/ St. Gervasi de Cassoles, 96-98 entlo. 3ª · 08022 Barcelona  
· Telf: 93 211 15 30 · Fax: 93 253 11 31  
Website: [www.proenecon.com](http://www.proenecon.com) · Email: [eneconib@proenecon.com](mailto:eneconib@proenecon.com)