ENECON® NEWS

CH-055

CHEMCLAD Stops Corrosion at Chilean Pasta Factory

At a major pasta factory located in Chile the floor of this refrigerated egg storage room floor was suffering from corrosion after many years of accidental egg breakage. Since eggs are corrosive in nature, the factory's maintenance team was looking for a fast yet cost effective way to repair and protect this area from future corrosion.

After contacting the local ENECON Distributor in Chile, it was recommended that the floor be protected with *CHEMCLAD SC*.

The floor was first throughly pressure washed and allowed to dry. A new metal sheeting baseboard was then installed. *ENECRETE DuraQuartz* was used to radius the transition between the floor and the wall.

ENECLAD Clear Floor Sealer was used to prime the floor surface quickly followed by one coat of *CHEMCLAD SC* with a broadcast of aluminum oxide to provide slip resistance. A final *CHEMCLAD SC* coat was then applied.

The factory's maintenance team was pleased with the results and is considering similar applications throughout the plant.

PROENECON SYSTEMS, S.A.· C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
·Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com

Copyright ©2009 by ENECON® Corporation.