ENECON® NEWS

CH-064

Desalination Plant in Cyprus Uses ENECRETE & CHEMCLAD to Stop Sulfuric Acid Attack

Client: Desalination Plant

Location: Cyprus

Problem: Sulfuric acid pump drip had badly damaged the cement base it sat on.

Solution: Damaged concrete was repaired with ENECRETE DuraQuartz. CHEMCLAD P4C was applied as a primer to the concrete. Two coats of CHEMCLAD XC we then applied to provide optimum chemical resistance.

Savings: This project was completed in 3 days much to the delight of the plant managers who saved thousands of dollars by avoiding a full replacement.

PROENECON SYSTEMS, S.A.· C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
·Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com

Copyright ©2013 by ENECON® Corporation.

REPAIR - DON'T REPLACE