ENECON® NEWS

CH-090

After 13 Years, CHEMCLAD Holds Up On MSC Hospital Ship's Laundry Decks

This Military Sealift Command (MSC) hospital ship has an ENECON repair that has performed beautifully for over 13 years...and counting.

The ship's laundry room decks were corroded from industrial washing machine spillage. Originally the ship's Port Engineer wanted to install a stainless steel liner atop the carbon steel deck. After consulting the local ENECON Field Engineering Specialist, it was recommended that the floors be grit blasted followed by 2 coats of CHEMCLAD SC.

With over 1,000 beds on this ship, the floors of this laundry room can be a corrosive place. CHEMCLAD SC has eliminated this threat for over a decade.

PROENECON SYSTEMS, S.A.· C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
·Telf: 93 211.15.30 · Fax: 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com

Copyright ©2017 by ENECON® Corporation.

REPAIR - DON'T REPLACE®