

## DuraQuartz Scores HIGH Marks From The LOWEST Point In The World!



The ENECON Israel Team recently completed this large concrete repair project at the Dead Sea Works. This is a critical containment area for large Chlorine tanks.

The concrete was severely deteriorated due to the highly corrosive environment found in the Dead Sea area. The Dead Sea contains so much salt and other minerals that a body literally cannot sink in it.

The project required 40 DuraQuartz systems and was completed to the total satisfaction of the plant engineers.

