



At one of the largest beer manufacturers in Costa Rica, the maintenance engineers were experiencing severe erosion and corrosion on a large concrete slab.

After many years of heavy truck traffic and corrosive

material spillage, this area had become pitted and severely deteriorated.

The local ENECON distributor was contacted to help find a fast, cost-effective and long lasting solution. It was recommended that

ENECON DuraQuartz be used to rebuild, repair and protect the concrete slab.

After removing any loose debris, the entire area was power washed.

Over 18 units of **DuraQuartz** were then used to repair the damaged area and provide excellent protection from future abuse.

PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona
· Telf: +34 93 211.15.30 · Fax: +34 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com