



Seattle Office Building Steps are Repaired with ENECRETE DuraQuartz

Client: Commercial office building

Location: Seattle, WA

Problem: High traffic main entrance steps were unsightly and beginning to deteriorate causing a potential tripping hazard. This entrance could not be shut down and sidewalk pedestrians could not be adversely effected by any repair process.

Solution: This \$20,000+ project began with dry ice blasting, completed in the unpredictable Seattle weather, to clean the steps prior to application. ENECRETE DuraQuartz with a customized broadcast system was then used to re-build the steps, create slip-resistance and protect them from future deterioration.



After

PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com