


ENECON[®] NEWS



Moroccan Flour Manufacturer Uses DuraFill to Repair & Protect Their Floors



Client: *Flour Manufacturer*

Location: *Morocco*

Problem: *1000 sq meter concrete and tile floors in factory warehouse were spalled, cracked, and pitted.*

Solution: *All loose material was removed and holes, cracks, and joints were repaired / filled with ENECRETE DuraFill. A thin coat of DuraFill was used to level the floors then a final DuraFill topcoat, tinted gray in the field, was applied.*



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.

· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com