

## 40 Units of ENECRETE<sup>®</sup> DuraFill<sup>®</sup> Used to Repair Cracked Concrete Floors in 8 Costa Rican Warehouses



**Client:** An 8 unit warehousing complex in Costa Rica.

**Problem:** 20 year old warehouse concrete floors were severely cracked due to several factors, including excess weight being stored.

**Solution:** It was decided that ENECRETE<sup>®</sup> DuraFill<sup>®</sup>, mixed with locally sourced quartz sand, was the most cost effective course of action to solve this problem. All of the cracks were first opened up mechanically with a grinding wheel. The loose material was vacuumed up. The DuraFill<sup>®</sup> / sand mixture was then poured into the cracks. Before the DuraFill<sup>®</sup> was fully cured it was sanded down seamlessly to the floor's height.

**Cost:** This project was in excess of \$85,000 USD saving the customer hundreds of thousands of dollars in new concrete costs.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.  
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: [www.proenecon.com](http://www.proenecon.com) · Email: [eneconib@proenecon.com](mailto:eneconib@proenecon.com)