

Southeastern U.S. Garbage Transfer Station Uses ENECRETE[®] DuraFill[®] to Repair Damaged Concrete Floor



Client: Southeastern U.S. municipal garbage transfer station.

Problem: Concrete degradation up to 12" deep from heavy equipment traffic and garbage pile up.

Solution: ENECRETE[®] DuraFill[®] with locally sourced quartz sand.

Savings: 9 units of DuraFill saved the municipality lengthy down-time and new concrete costs. The area was back in service in 24 hours.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com