

In 2004, ENECON was contacted by maintenance engineers to provide a solution for crumbling concrete steps at a stadium in the western U.S. 12 years and hundreds of sporting events and concerts later, the DuraQuartz step repair looks like it did the day it was installed.

A repair like this may be small, but it is one of the most important repairs a facility can make. Damaged steps account for millions of injuries a year. Maintenance engineers want to do their best to prevent these types of accidents on their properties. ENECON is there to help.

After 12 Years, Football Stadium Concrete Repairs With DuraQuartz Looks Like New



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com