


Major Hospital Center
in Houston, Texas,
Turns to ENECLAD FPS
To Waterproof & Protect
Large Mechanical
Equipment Room



This large cancer center located in Houston was experiencing serious leak problems in their mechanical room located on the second floor.

The facilities engineers needed a cost effective, long-term solution utilizing state-of-the-art materials. They turned to the ENECON Engineering Team for help.

ENECRETE DuraQuartz was used to repair all the cracks in the floor followed by a one-coat application of **ENECLAD FPS** to seal and protect the entire 15,000 square foot floor area.

PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona.

Tel: 93.211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com