
ELECON REVS





following report:

"Over the years, the insulation on the plant's digesters had been compromised in a number of areas and was becoming saturated with water. As a result, it was deteriorating at an accelerated rate and was diminishing the efficiency of their operating unit. If a solution was not provided. the insulation would have continued to deteriorate and would have eventually needed to be replaced - a

Consequently, the plant's Wastewater Treatment Supervisor elected to take a 'proactive' preventive maintenance approach and utilize ENESEAL HR to protect the insulation - at a fraction of the cost of replacing the insulation if it had been allowed to continue to deteriorate.

The on-site staff of the wastewater treatment plant applied the ENESEAL themselves and are extremely satisfied with it's performance."



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona. Telf: 93.211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com