
## ELECON REVIS

ES-034



**Client:** Major metro area detention center.

Location: Southern California.

**Problem:** Cogen plant cooling tower was

corroding at an accelerated rate.

**Solution:** After surface prep that consisted of

power washing and grit blasting, ENESEAL CR was applied to provide

long term corrosion resistance.

**Cost:** \$15,000 in product.

Labor provided by plant personnel.











PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona. Telf: 93.211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com  $\cdot$  Email: eneconib@proenecon.com