

These large oil storage tanks located at a hydroelectric facility in Tennessee were in need of a new protective coating. The old lead-based paint was beginning to peel and surface corrosion was visible in certain areas.


Due to the safety risks associated with working with the surrounding high-voltage equipment, special temporary

containment was constructed prior to the tanks' surface preparation. The old lead-based paint was removed by pressure washing and then properly disposed of.

Two coats of ENESEAL CR were then applied providing a highly durable, corrosion resistant, elastomeric 'skin'.

Problem Solved.

Tennessee Hydroelectric Plant Uses ENESEAL CR to Protect Oil Tanks



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol.Ind. La Torre · 08760 - MARTORELL. Barcelona.

Tel: 93.211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com