





Air Extraction Fan Blades From Australian Mining Operation Re-Built & Protected With CeramAlloy

These aluminum air extraction blades had eroded due to the fine particles that were sometimes present in the air in the mine. The mine's maintenance

engineers wanted a quick and cost effective method to repair these fan blades and provide them with long-term protection from future erosion damage. They selected

CeramAlloy CP+AC and CL+AC because of the ease of application and the outstanding erosion and corrosion resistance that the CeramAlloy system provides.

These step-by-step photos clearly illustrate the outstanding results.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com