

European Refinery Repairs & Protects Cooling Water Pumps With CeramAlloy

At this major refinery located near Antwerp, Belgium, erosion and corrosion problems were a constant maintenance issue for the plant's engineers. A number of years ago, they decided to repair and protect their cooling water pumps with

CeramAlloy CP+AC and CL+AC.

The maintenance engineers have been delighted with the results and this series of photos illustrates a typical cooling water pump repair procedure.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com