

METALCLAD CeramAlloy Stops Corrosion on Power Plant Heat Exchangers



Client: 550 Megawatt Natural Gas Power Plant.

Location: California

Problem: Accelerated corrosion of 2 year old heat exchangers (8 units) due to prolonged exposure to recycled water.

Solution: 40+ mil, 2 coat application of a METALCLAD CeramAlloy CL+AC system.

Cost: \$66,000 product only.

