

## Waste Water Treatment Plant Salvages 'Unsalvageable' Pump Suction Housing with CeramAlloy

**Client:** Waste Water Treatment Facility

**Location:** Southwest Florida

**Problem:** Severely eroded & corroded pump suction housing.

**Solution:** Grit blast – repair all eroded areas back to original shape and profile with CeramAlloy CP+AC. Reinforcement mesh was used to bridge holed or severely eroded areas. Two coats of CeramAlloy CL+AC were then applied to completely encapsulate the casing to protect it from future erosion and corrosion damage.

**Savings:** A new housing would have had to have been manufactured to spec at a cost of approximately \$10,000 with a 14 week lead time. Less than \$1,000 worth of CeramAlloy was used to repair this pump *and it took only one day!*



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.  
·Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: [www.proenecon.com](http://www.proenecon.com) · Email: [eneconib@proenecon.com](mailto:eneconib@proenecon.com)