



Tugboat Operator Selects CeramAlloy to Combat Erosion/Corrosion on Their Kort Nozzles

This tugboat belonging to a major international marine company in Florida was suffering from the effects of erosion & corrosion on its Kort nozzles. The local ENECON Fluid Flow Systems Specialist was called in to help find a solution.

After preparing the surface by grit blasting to acquire a 'white metal' finish, two coats of CeramAlloy CL+AC were applied.

The owner of the vessel was so pleased with the final results that another tugboat's Kort nozzles have already been scheduled for repair.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona.
· Telf: 93 211.15.30 · Fax: 93.253.11.31

Website: www.proenecon.com · Email: eneconib@proenecon.com