

One Of Florida's Oldest Wastewater Treatment Plants Uses DuraWrap & DuraQuartz To Salvage Sludge Discharge Pipes...Saving \$500,000



Built in 1927, one of the oldest was facing a potential \$500,000+ sludge discharge pipe replacement. These pipes are embedded in a concrete tank wall. Replacement of these pipes would require that the tank grit blasted. The pipes were then wall be demolished and rebuilt.

The ENECON Field Engineering wastewater treatment plants in Florida Specialist recommended the DuraWrap **Carbon Fiber Pipe Wrap System to** save these critical pipes.

> The concrete walls and pipes were first This repair cost the plant approxprimed with DuraWrap Primer and the

carbon fiber was wetted out with the DuraWrap Polymer. The tank's vertical concrete wall was then repaired with DuraQuartz LW.

imately \$6,000, half-a-million dollars cheaper than a pipe replacement!





DuraWrap Primer on the pipes.








DuraQuartz LW used to repair the vertical tank wall.

DuraWrap Carbon Fiber being applied.



The repaired pipes and tank wall.



Copyright ©2018 by ENECON[®] Corporation.

