

Broken Curbs In Montana Are Repaired & Protected With DuraFill, DuraQuartz, FLEXICLAD PC & ENESEAL CR

Damaged concrete curbs outside of a small Montana business were cracked and crumbling after years of expansion and contraction from freeze/thaw cycles. The local ENECON Distributor was called in to provide a solution.

After removing the loose material and cleaning the areas, the curbs were repaired with ENECRETE DuraFill & DuraQuartz. All of the curb/building joints were filled with FLEXICLAD PC to allow for expansion. A final overcoat of ENESEAL CR was used to provide an attractive appearance.



PROENECON SYSTEMS, S.A. · C/ Electricitat, 6. Pol. Ind. La Torre · 08760 - MARTORELL. Barcelona
· Telf: +34 93 211.15.30 · Fax: +34 93.253.11.31
Website: www.proenecon.com · Email: eneconib@proenecon.com